



Department of consumer and corporate affairs / Ministère de la consommation et des corporations



SPG-152  
1147-57/R2-M29  
SL-100-981  
SL-100-SPG

OTTAWA, April 7, 1972.

SPECIAL APPROVAL

Granted to: Gaz Metropolitain, Inc.,  
1717 du Havre,  
Montreal 134, P.Q.

Attention: Mr. A. Lodomez,  
Meter Shop.

Subject: Fischer and Porter Model 1543-FA-13A  
Gas Survey Recorder with Rockwell Type I  
Temcorector fitted with Rockwell Model  
3550 Disc Rotaswitch Contactor

Special Approval has been granted by the Standards Branch  
to Gaz Metropolitain to apply the subject instrumentation in  
four installations the details of which are as follows:

1. Dominion Textile Ltd.,  
Valleyfield, P.Q.

(a) Fisher & Porter Recorder - Inspection No. 184-149390  
Serial No. 6911 B-2010T1  
Model No. 1543 - FA13A  
1 Pulse records 10,000 cu. ft.

(b) Rockwell Temcorector Type I-100 psig range  
Inspection No. 96-149377  
Serial No. 7255

(c) Impulse Contactor - Disc Rotaswitch  
Model 3550  
1 revolution gear-driven magnet  
1 pulse 10,000 cu. ft. (corrected volume)



2. Molson Brewries of Canada Ltd.,  
1555 Notre Dame Street E.,  
Montreal, P.Q.

(a) Fisher & Porter Recorder  
Model No. 1543-FA13A  
Inspection No. 184 - 149389  
Serial No. 69NB2010T2  
1 pulse records 1,000 cu. ft. (corrected)

(b) Rockwell Temcorector Type I Range  
0 to 20 psig  
Inspection No. 96 - 152137  
Serial No. 5006

(c) Impulse Contactor  
Disc Rotaswitch Model 3550  
1 revolution gear-driven magnet  
1 pulse 1,000 cu. ft. (corrected volume)

3. General Foods Ltd.,  
795 - 90th Avenue,  
Ville LaSalle, P.Q.

(a) Fisher & Porter Recorder  
Model No. 1543 - FA13A  
Inspection No. 184 - 1521  
Serial No. 7110-B-2398-T1  
1 pulse records 1,000 cu. ft. (corrected)

(b) Rockwell Temcorector Type I Range  
0 to 100 psig  
Inspection No. 96 - 152177  
Serial No. 5009

(c) Impulse Contactor  
Disc Rotaswitch Model 3550  
1 revolution gear-driven magnet  
1 pulse 1,000 cu. ft. (corrected volume)

4. Northern Electric Company Ltd.,  
150 Montreal-Toronto Highway,  
Lachine, P.Q.

(a) Model No. 1543 - FA13A  
Inspection No. 184 - 152182  
Serial No. 7110B - 2398T2  
1 pulse in put records 1,000 cu. ft. (corrected volume)

(b) Rockwell Temcorector Type I Range  
0 to 20 psig  
Inspection No. 96 - 197212  
Serial No. 5011



- (c) Impulse Contactor
- Disc Rotaswitch Model 3550
- 1 revolution gear-driven magnet
- 1 pulse 1,000 cu. ft. (corrected volume)

In addition to the test normally required for Temcorectors and Survey Recorders, test and inspection shall be made with the appropriate components properly connected together and performing as a entity.

*W. J. S. Fraser*

W.J.S. Fraser,  
Chief,  
Electricity and Gas Division  
Standards Branch.

c.c. Mr. A. Laferriere, E&G, Montreal



December 28, 1972

Mr. W.J.S. Fraser *WJF*  
Chief Electricity & Gas  
Dept. of Consumers & Corporate Affairs  
Standards Branch  
Standards Building  
Tunney's Pasture  
Holland Ave., Ottawa  
Ontario, K1A 0C 9

1147-57/R2-251  
EL 1147-57/R2 251  
1147 2

Re: S.P.G. 152  
1147-57/R2-M29  
SL-100-981  
SL-100-S.P.G.

Dear Sir,

Please be advised that due to a change of clauses in the Sales contract with Dominion Textile, Valleyfield, P.Q., the Temcorector Disc Rota switch and the Fischer & Porter recorder have been removed. These are no longer required at this location and will not be reinstalled there.

You are therefore requested to please cancel this portion of this special approval.

Yours truly,



A. Lodomez,

AL/jb

DEPARTMENT OF  
CONSUMERS AND CORPORATE AFFAIRS

JAN 5 1973

